

REGULADOR BUTANO



CODIGO	MEDIDA	U/BOLSA	PVP
27010001	30GRS	50	11,55
27010002	50GRS	50	12,69
27010003	LIBRE	20	12,08

CODO SOLDAR



CODIGO	MEDIDA	U/BOLSA	PVP
27010016	10	25	3,27

TE SOLDAR



CODIGO	MEDIDA	U/BOLSA	PVP
27010017	10	25	3,62
27010018	12	25	4,16

UNION SOLDAR



CODIGO	MEDIDA	U/BOLSA	PVP
27010014	10	25	1,14
27010015	12	25	1,35

BOQUILLA SOLDAR



CODIGO	MEDIDA	U/BOLSA	PVP
27010010	10	25	0,72
27010011	12	25	0,88

BOQUILLA LISA



CODIGO	MEDIDA	U/BOLSA	PVP
27010012	10	25	0,93
27010013	12	25	1,18

BOQUILLA HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010025	10	25	3,00
27010026	12	25	3,39

UNION HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010027	10	25	4,23
27010028	12	25	4,81

REDUCCION HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010029	10_12	25	4,82

CODO HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010030	10	25	6,32
27010031	12	25	6,84

TE HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010032	10	25	7,55
27010033	12	25	8,76

REDUCCION HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010034	10- 1/2"	25	4,64
27010035	12-1/2"	25	4,90
27010036	10-3/4"	25	5,59
27010037	12-3/4"	25	5,67

TUERCA HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010038	10	25	1,10
27010039	12	25	1,14

DERIVACION TUBO GOMA



CODIGO	MEDIDA	U/BOLSA	PVP
27010044	10	25	8,44

DERIVACION ZAMAK



CODIGO	MEDIDA	U/BOLSA	PVP
27010045	—	25	3,64

LLAVE GAS SOLDAR



CODIGO	MEDIDA	U/BOLSA	PVP
27010055	10	25	19,13
27010056	12	25	19,37

LLAVE GAS HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010057	10	25	14,13
27010058	12	25	17,61

ABRAZADERA A - T



CODIGO	MEDIDA	U/BOLSA	PVP
27010050	10	5	1,29
27010051	12	5	1,29

TUERCA JUNTA PLANA V-82



CODIGO	MEDIDA	U/BOLSA	PVP
27010061	10_12	25	1,76

BICONO HERMETO



CODIGO	MEDIDA	U/BOLSA	PVP
27010040	10	25	0,48
27010041	12	25	0,51

MANGUITO SOLDAR V-82



CODIGO	MEDIDA	U/BOLSA	PVP
27010059	10- 1/2"	25	0,78
27010060	12-1/2"	25	0,76